

SAMPLE — Synthetic construction appendix

Week 2026-09-07 to 2026-09-13




Photo 01

Asset: 0001

North elevation: concrete columns and level-one formwork in place. Confirm the open bays before next week.




Photo 02

Asset: 0002

Fundação — seção norte. Reinforcement layout visible; concrete placement to be reviewed.




Photo 03

Asset: 0003

Stair core: lower flight and landing reference. Maintain this view for the weekly comparison.

SAMPLE — Synthetic construction appendix

Week 2026-09-07 to 2026-09-13

Photo 04

Asset: 0004

East wall: masonry sample panel and perimeter access.




Photo 05

Asset: 0005

Service trench: alignment reference along the east boundary.





Photo 06

Asset: 0006

Roof steel: primary beam connections viewed from ground level.



SAMPLE — Synthetic construction appendix

Week 2026-09-07 to 2026-09-13




Photo 07

Asset: 0007

Access ramp: temporary edge protection and approach.




Photo 08

Asset: 0008

South boundary: site access and perimeter reference.